

Jubilee Survey- February,2005

Cost Item	High Priority	Budget Cost	Description	Q1	Q2	Q3	Q4	Q5
1			100 Chimney stack	L	L	L	M	L
2			110 Flashings 7 Aprons	M	M	L	M	L
3	375		375 Roof Inspection	H	H	L	M	M
4	4000		4000 Rear Extn Roof	H	H	L	M	M
5	100		100 Removal of Ivy	L	H	L	M	L
6			6400 Gutters & rainware-Froi	M	M	L	M	L
7			650 Gutters & rainware-Rea	M	M	L	M	L
8	n/a							
9	n/a			M	M	L	M	L
10			900 Soffits-as 6	L	M	L	M	L
11			1200 Bargeboards	L	M	L	M	L
12								
13			650 External Walls-pointing	L	M	L	M	L
14			950 Subsidence-Underpinni	L	M	L	M	L
15			9500 Subsidence/Underpinni	L	M	L	M	
16			3200 External doors & Windc	M	M	L	M	L
17			External Decoration					
18 See 23			4100					
19	19500		19500 Main hall Floor-Struct & H	H	H	H	H	H
20	9700		9700 Main Hall Floor Finishe	H	H	H	H	H
21			200 Staircase	L	L	H	L	L
22				L	L	L	L	L
23	1600		1600 Damp Injection Treatme	L	H	H	M	H
24			13500 Internal decoration	L	M	L	M	L
25	13600		13600 Main Hall Ceiling	L	H	M	L	L
26			500 Plumbing	L	L	L	L	L
27			250 Electrical	L	L	L	L	L
28			850 Access issues DDA-internal					
29			2000 Access issues-Internal					
30			550 External Paths & paving	M	L	M	L	L
31			800 Boundary Walls	L	L	L	L	L
32			350 Drainage-Linked to 14	L	L	L	L	L
33			3500 Out Building	L	L	L	L	L
Total	48875	99135						
Wish List								
1	7000		7000 Lighting					

Q1-If not done in the next five years,will it cause serious inconvenience to hall Users? Low/Medium/High

Q2-If not done in next five years,will it cause deterioration to the fabric of the hall? Low/Medium/High

Q3-If not done will it cause Health & safety issues? Low/Medium/High

Q4-Will cost of repair increase in real terms as a result of delay? Low/Medium/High

Q5-If not done in next five years ,will the hall become unusable? Low/Medium /High

